

GC 163 RWA DE Wärmemelder DE Beiblatt

184143-00



Wärmemelder GC 163 RWA



Dazu Montageanleitungen MBZ 300, THZ und THZ Comfort beachten, siehe www.geze.com.

Technische Daten

Wärmemelder GC 163 RWA mit: Mat. Nr. 184139

- Wärmemelder GC 003 D RWA

 Sockel GC 160 B RWA 	
Farbe	weiß, RAL 9010
Abmessungen (mit Sockel, DxH)	110 mm x 54 mm
Gewicht	130 g
Standard	EN 54-5
Funktionsprinzip	Alarm, falls Umgebungstemperatur die Alarmtemperatur überschreitet oder falls sich die Umgebungstemper atur sehr schnell erhöht, speichernd
Alarmtemparatur	57°C
EN 54-5 Klasse	A1R
Eingangsspannung	24 V DC (10-30 V DC)
Eingangsstrom	Ruhe: max. 60 µA; Alarm: max. 20 mA
Einbaulage	Deckenmontage
Umgebungstemperatur	-30°C bis 70°C
Alarmwiderstand	1,2 kΩ
Stromerhöhungsprinzip	2-Leiter-Technik Stromerhöhung mit Selbsthaltung
Alarmrücksetzung	durch Taste in Zentrale
Verwendung	nur mit GEZE Notstromsteuerzentrale
Meldertest	Alarmauslösung - mit Testmagnet in der Nähe des Magnetsensors - mit Wärmemelderprüfgerät

Germany GEZE GmbH Tel. +49 (0) 7152 203 594 GEZE GmbH

Niederlassung Süd-Ost Tel. +49 (0) 7152 203 6440 E-Mail: muenchen.de@geze GEZE GmbH Tel. +49 (0) 7152 203 6840 E-Mail: berlin.de@geze.com

GEZE GmbH GEZE GmbH

Niederlassung West Tel. +49 (0) 7152 203 6770 E-Mail: duesseldorf.de@ge GEZE GmbH Niederlassung Nord Tel. +49 (0) 7152 203 6600 E-Mail: hamburg.de@geze.

GEZE Service GmbH Tel. +49 (0) 1802 923392 E-Mail: service-info.de@g GEZE Austria E-Mail: austria.at@geze.com

www.geze.at Baltic States Lithuania / Latvia / Estonia E-Mail: baltic-states@geze.com

Benelux GEZE Benelux B.V.

www.geze.bg

www.geze.it GE7E Korea Ltd E-Mail: info.kr@ge www.geze.com

www.geze.it

Poland GEZE Polska Sp.z o.o. E-Mail: geze.pl@geze.cor

GEZE Industries (Tianjin) Co., Ltd.

GEZE Industries (Tianjin) Co., Ltd. Branch Office Shanghai E-Mail: chinasales@geze.com.cn

GEZE Industries (Tianiin) Co., Ltd

GEZE Industries (Tianjin) Co., Ltd. Branch Office Beijing

Branch Office Guangzhou E-Mail: chinasales@geze.co

www.geze.com.cn

E-Mail: chinasales@g

www.aeze.com.cn

GEZE France S.A.R.L.

www.geze.hu

E-Mail: france.fr@geze.c www.geze.fr

GEZE Iberia S.R.L. E-Mail: info.es@geze.cor www.geze.es

GEZE India Private Ltd.

Italy GEZE Italia S.r.I E-Mail: italia.it@geze.com

E-Mail: office-india@g

GEZE Hungary Kft. E-Mail: office-hungary@geze.cor

F-Mail: chinasales@geze.com.cr

GEZE Romania S.R.L. F-Mail: office-ron

Russia OOO GEZE RUS E-Mail: office-russia@geze.com www.geze.ru

Scandinavia Sweder GEZE Scandinavia AB E-Mail: sverige.se@geze www.geze.se

Scandinavia Norway GEZE Scandinavia AB avd. Norge E-Mail: norge.se@geze.co

www.geze.no Scandinavia Denmark

GEZE Danmark E-Mail: danmark.se@geze.com www.geze.dk

Singapore GEZE (Asia Pacific) Pte, Ltd. E-Mail: gezesea@geze.com.sg www.geze.com

South Africa GEZE South Africa (Pty) Ltd. E-Mail: info@gezesa.co.za www.geze.co.za

Switzerland GEZE Schweiz AG E-Mail: schweiz.ch@d www.geze.ch

Turkey GEZE Kapı ve Pencere Sistemleri E-Mail: office-turkey@geze.com www.geze.com

LLC GEZE Ukraine E-Mail: office-ukraine@geze.com


United Arab Emirates/GCC GEZE Middle East E-Mail: gezeme@gez www.geze.ae

United Kingdom GEZE UK Ltd. E-Mail: info.uk@geze www.geze.com

GEZE GmbH Reinhold-Vöster-Straße 2129 71229 Leonberg Germany

Tel.: 0049 7152 203 0 Fax: 0049 7152 203 310 www.geze.com





Magnetsensor zum Testen (hinter GEZE Logo) LED zur Zustandsanzeige

Verwendung

Der GC 163 RWA ist ein Wärmemelder zur Verwendung in GEZE RWA-Anlagen.

Wärmemelder messen die Umgebungstemperatur und reagieren, wenn die Temperatur einen bestimmten maximalen Wert überschreitet oder innerhalb einer bestimmten Zeit sehr stark ansteigt. Diese Temperaturmelder arbeiten nach dem Stromerhöhungsprinzip. Im Alarmfall ändert sich die Stromaufnahme des Melders.

Normalerweise breiten sich bei einem Brand Rauch- und Brandgase schnell aus. Die Temperaturerhöhung erfolgt erst zeitversetzt.

Soweit möglich sollen allgemein für RWA-Anlagen Rauchmelder verwendet werden. In Bereichen mit Störgrößen wie Dampf, Staub, Betauung oder betriebsbedingter Rauchentwicklung (Werkstätten, Küchen) kann es aber sinnvoll sein, statt Rauchmelder Wärmemelder zu verwenden.

Abschlusswiderstand zur Leitungsüberwachung

Im Sockel GC 160 B des letzten Rauch-/Wärmemelders einer Linie muss ein 10 k Ω Abschlusswiderstand eingebaut werden. Der Widerstand liegt der Zentrale bei.


Signalisierung

	LED	Stromaufnahme
Spannungslos	aus	0 mA
Normalbetrieb	aus	70 μΑ
Alarm	ein	15-20 mA

Anschluss Notstromsteuerzentrale MBZ300, THZ, THZ Comfort:



Die maximale Anzahl der Rauch- bzw. Wärmemelder je Linie ist abhängig von der Zentrale.




- Erster Wärmemelder
- Letzter Wärmemelder
- Endwiderstand im letzten Melder einsetzen
- Klemmleiste GEZE Notstromsteuerzentrale (siehe zugehörigen Anschlussplan)
- Rauchmelderanschluss



Testen

Zum Testen, Wärmemelderprüfgerät eines anerkannten Herstellers verwenden und entsprechend den Hersteller-Anweisungen

- Die rote LED am Melder muss in den Alarmzustand gehen.
- An der RWA-Zentrale muss ein Alarm aktiviert werden.
- Nach Abschluss des Tests, Alarm an Zentrale zurücksetzten und Melderlinien-Reset durchführen.



GC 163 RWA EN Heat detector **EN** Supplementary sheet

184143-00



Heat detector GC 163 RWA



Refer to installation instructions MBZ 300, THZ and THZ Comfort, see www.geze.com.

Technical data

Heat detector GC 163 RWA with: Mat. no. 184139

Heat detector GC 003 D RWABase GC 160 B RWA	
Colour	white, RAL 9010
Dimensions (with base, DxH)	110 mm x 54 mm
Weight	130 g
Standard	EN 54-5
Functional principle	Alarm, if ambient temperature exceeds the alarm temperature or if the ambient temperature increases very quickly, retentive
Alarm temperature	57°C
EN 54-5 classification	A1R
Input voltage	24 V DC (10-30 V DC)
Input current	Static: max. 60 µA; Alarm: max. 20 mA
Installation position	Ceiling mounting
Ambient temperature	-30°C to 70°C
Alarm resistance	1.2 kΩ
Principle of current increase	2-conductor technology current increase with self-locking
Alarm reset	by key in control unit
Use	only with GEZE emergency power supply control unit
Detector test	Alarm triggering - using test magnet near the magnetic sensor - using heat detector testing device

Germany GEZE GmbH Niederlassung Süd-West Tel. +49 (0) 7152 203 594 GEZE GmbH

Niederlassung Süd-Ost Tel. +49 (0) 7152 203 6440 E-Mail: muenchen.de@geze

GEZE GmbH Tel. +49 (0) 7152 203 6840 E-Mail: berlin.de@geze.com GEZE GmbH

GEZE GmbH Niederlassung West Tel. +49 (0) 7152 203 6770 E-Mail: duesseldorf.de@gez

GEZE GmbH Niederlassung Nord Tel. +49 (0) 7152 203 6600 E-Mail: hamburg.de@geze. GEZE Service GmbH Tel. +49 (0) 1802 923392 E-Mail: service-info.de@ge:

GEZE Austria E-Mail: austria.at@geze.com

/ww.geze.at Baltic States Lithuania / Latvia / Estonia E-Mail: baltic-states@geze.com

Benelux GEZE Benelux B.V.

www.geze.bg

GE7E Korea Ltd

E-Mail: info.kr@ge www.geze.com **Poland** GEZE Polska Sp.z o.o.

E-Mail: geze.pl@geze.cor

GEZE Industries (Tianjin) Co., Ltd.

GEZE Industries (Tianjin) Co., Ltd. Branch Office Shanghai E-Mail: chinasales@geze.com.cn

GEZE Industries (Tianiin) Co., Ltd

GEZE Industries (Tianjin) Co., Ltd. Branch Office Beijing

Branch Office Guangzhou E-Mail: chinasales@geze.co

E-Mail: chinasales@g

GEZE France S.A.R.L.

www.geze.hu

E-Mail: france.fr@geze.c www.geze.fr

GEZE Iberia S.R.L. E-Mail: info.es@geze.com www.geze.es

GEZE India Private Ltd.

E-Mail: office-india@g

Italy GEZE Italia S.r.I E-Mail: italia.it@geze.com

www.geze.it

www.geze.it

GEZE Hungary Kft. E-Mail: office-hungary@geze.cor

www.aeze.com.cn

www.geze.com.cn

F-Mail: chinasales@geze.com.cr

GEZE Romania S.R.L.

Russia OOO GEZE RUS E-Mail: office-russia@geze.com

Scandinavia Norway GEZE Scandinavia AB avd. Norge

F-Mail: office-ron

www.geze.ru

Scandinavia Sweder

GEZE Scandinavia AB E-Mail: sverige.se@geze www.geze.se

E-Mail: norge.se@geze.co

Scandinavia Denmark GEZE Danmark E-Mail: danmark.se@geze.com www.geze.dk

Singapore GEZE (Asia Pacific) Pte, Ltd.

E-Mail: gezesea@geze.com.sg

South Africa GEZE South Africa (Pty) Ltd. E-Mail: info@gezesa.co.za www.geze.co.za

E-Mail: schweiz.ch@geze.c

Turkey GEZE Kapı ve Pencere Sistemleri E-Mail: office-turkey@geze.com

United Arab Emirates/GCC

GEZE Middle East E-Mail: gezeme@geze www.geze.ae

United Kingdom GEZE UK Ltd. E-Mail: info.uk@geze www.geze.com

www.geze.no

www.geze.com

Switzerland GEZE Schweiz AG


www.geze.ch

www.geze.com LLC GEZE Ukraine E-Mail: office-ukraine@geze.com

GEZE GmbH Reinhold-Vöster-Straße 2129 71229 Leonberg Germany

Tel.: 0049 7152 203 0 Fax: 0049 7152 203 310 www.geze.com





Magnetic sensor for testing (behind the GEZE logo) LED for displaying state

Use

The GC 163 RWA is a heat detector for use in GEZE RWA systems. Heat detectors measure the ambient temperature and respond if the temperature exceeds a certain maximum value or increases quickly within a certain time. These thermal detectors work according to the principle of current increase. In the event of an alarm, the current consumption of the detector changes.

Usually, smoke and fire gases spread guickly when a fire breaks out. It is only later that the temperature increases. As far as possible, smoke detectors should generally be used for RWA systems. In areas where disruption such as steam, dust or operation-related smoke development (workshops, kitchens) occurs, it may, however, be sensible to use heat detectors rather than smoke detectors.

Terminating resistor for line monitoring

There must be a 10 k Ω terminating resistor built into the base GC 160 B of the last smoke detector in a line. The resistor is included with the control unit.


Signalling

	LEDs	Current consumption
Voltage-free	off	0 mA
Normal operation	off	70 μΑ
Alarm	on	15-20 mA

Connection of the emergency power supply control unit MBZ300, THZ, THZ Comfort:



The maximum number of smoke or heat detectors per line depends on the control unit.



- First heat detector
- Last heat detector
- Insert the terminal resistor in the last detector
- Terminal strip GEZE emergency power supply control unit (see respective wiring diagram)
- Smoke detector connection



Use heat detector testing device from a recognised manufacturer for testing in accordance with the manufacturer's instructions.

- The red LED on the detector must change to the alarm state.
- An alarm must be activated on the RWA control unit.
- After the test has been completed, reset the alarm on the control unit and carry out a detector line reset.